

Estabrook Dam Stop Log Section and components



Photo 1: View of stop log section in June 2010 prior to being removed. Right arrow is pointing to typical stop log stanchion. Middle arrow is pointing to timber stop logs. Left arrow pointing at steel channel section of the stop logs.



Photo 2: View of steel channels (left arrow) for the stop logs and severely corroded stop log stanchions (right arrow)